Tips for ALL Laser Cut Projects

Approval Lab Assistant

Cutting Lab Assistant

- Please find and keep all laser materials as flat as possible. Warping will lead to difficult/failed parts
- There is a possibility to cut material thicker than .25", however this must be tested and approved first
- ABSOLUTELY NO PRODUCTS CONTAINING CHLORINE (PVC, CPE, CPVC, NEOPRENE)

LA Name:	Material Detail	File	Laser Settings	Notes
Date approved:				
Estimated time:				
Material Received:				
Material has been properly verified by sticker, receipt, etc.	.125" clear acrylic	Sachs_Robby_9320	Power/Speed/PPI	
LA Name: Print Date : Start Time : End Time: Email sent				
Reminder - Always set z height, use ventilation and air assist.				